

---

**Model:** STR-DB830, STR-DB840, STR-DB930, STR-DB940, STR-DE135, STR-DE245, STR-DE335, STR-DE435, STR-DE445, STR-DE545, STR-DE635, STR-DE835, STR-DE845, STR-DE935, STR-DE945, STR-SE391, STR-SE491, STR-SE501, STR-SE591, STR-V333ES, STR-V444ES, STR-V555ES**No. 649****Subject:** Part Number Correction**Date:** January 8, 2001**Symptom:**  
(XXXX)

The part number listed in the service manual for the FM antenna is incorrect.

**Solution:**

Use the part number listed below when ordering a replacement FM antenna.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
N/A	FM ANTENNA	1-501-594-11	1-793-184-21